

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	((airplane near3 control near3 surface) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:07
L2	1	1 and dynamometric near3 pin	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:17
L3	21	((airplane near3 control near3 surface) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:50
L4	1	3 and dynamometric near3 pin	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:20
L5	1	3 and dynamometric	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:17
L6	4	3 and pin	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:46
L7	2	("3695096").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/07/15 19:21
L8	2	dynamometric near3 pin.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:20
L9	63	dynamometric .clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:21
L10	1	3 and 9	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:45
L11	2	("6140942").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/07/15 19:22

EAST Search History

L12	77	(73/802).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/07/15 19:46
L13	0	3 and 12	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:46
L14	1	12 and (control near3 surface).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 19:46
L15	8780	((control near3 surface) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:07
L16	4	12 and 15	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:05
L17	23	(airplane near3 control near3 surface) .clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:07
L18	9	17 and (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:11
L19	3	18 and (cylindrical\$4 elongated radial\$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:09
L20	772556	(cylindrical\$4 elongated radial\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:09
L21	68239	20 and threaded.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:10
L22	19989	21 and (groove channel).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:10
L23	287	22 and ((force load stress strain compress\$4 tensi\$3) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:12

EAST Search History

L24	27	23 and wire.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:12
L25	1184825	24 (nut screw\$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:13
L26	24	24 and (nut screw\$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:13
L27	15	26 and control\$5	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:14
L28	5	23 and airplane	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/07/15 20:14